

Training SPECHT® 600 (SIEMENS 840D sl)

Mechanical Maintenance – M2 (Repair and Replacement)

Target group: The Training is provided for mechanics of SPECHT machine centers

Number of Participants: Maximum 5 participants.

Training Period: The nominal training period of course M2 is 5 days (each 7 hours).
Deviations require prior consultation.

Prerequisites:

- Completed vocational training as an industrial mechanic
- Additional training as a technician/ engineer
- Knowledge of measuring instruments
- Experience in the detection of wear marks

Training Target:

- Safety regulations for maintenance personnel
- Use of suitable auxiliary and measuring equipment (from catalog)
- Use of the machine logbook
- Diagnosis possibilities, fault and wear detection
- Adjustments for repairs (Safety Integrated monitoring)
- Repairs on axis and spindles
- Repairs to doors, hatches, fixtures
- Machine check after collision

Training contents:

- Safety instructions
- Alarms, messages, alarm protocol
- Fixing of errors, cancelling messages
- Repairs on main axes (servo or linear drives)
 - Replacement of motors
 - Replacement of glass scale
 - Switching the active encoder
 - Replacement of ball screw assembly
 - Replacement of linear guides
 - Replacement of linear motors
 - Replacement of weight compensation
 - Setting the axis zero points (absolute encoder)
 - Use reference points to gantry axes
 - Adjustment of the gauge X1 / X2 and Y1 / Y2

- Synchronizing the measuring systems X, Y
 - Use of the crash bore for referencing
- Repairs on rotary axes
 - Removing / installing bridge
 - Replacement encoder, sealing center pin
 - Replacement of pneumatic clamping
 - Motor exchange (rotor / stator)
 - Adjust commutation angle on motors connected in parallel mode and individually operated
- Repairs at auxilliary axes (magazine)
 - Chain magazine HSK 63
 - Motor exchange at CT1, CT2, CT3, YT1 und ZT3
 - Setup axis zero points and transfer positions (*POS_PREP*)
 - cone cleaner
 - Tool breakage control
 - Chain magazine HSK 100
 - Motor exchange CT1, ZT1
 - indexing of chain
 - Motor exchange VT1
 - Setup axis zero points and transfer positions (*POS_PREP*)
 - cone cleaner
 - Tool breakage control
- Repairs at spindles
 - Replacement motor spindles CS1 (comp.) and CS2
 - Setting the spindle geometry CS1 and CS2
 - Setting zero point of the compensation axis W1 to CS1
 - Adjustment CS2 in Z direction
 - Adjust the analogue encoder of the spindle collet
 - Adjust spindle orientation
 - Tool seat check
- Machine check after collision
 - Check spindle geometry
 - Seat points of the clamping device: "Small geometry"
 - Recognize and correct tensions of the gantry axes
 - QC20-check